
INSTALLATION INSTRUCTIONS

FOR IRONING BOARD S08560 (Using machine screws)

Step 1:



Step 2: Drill through four 8mm holes.

(Bottom Board)


Min. 560 (22")

98(4X)

08(4X)

Center Line
(Front Edge)

Step 3:



Step 4: Pull out support wire rack.

